




Swing Check Operation Policy



Specifications

1. Measurements **MUST** be exact and will be subject to a field inspection
2. A blue reflective marker must be in place to identify location
3. See CVFD Policy 3104.00

