




## Swing Check Operation Policy



### Specifications

1. Measurements MUST be exact and will be subject to a field inspection
2. A blue reflective marker must be in place to identify location
3. See CVFD Policy 3104.00